

APPENDICES

Appendix A – Site Walkover Photographs

Appendix B – Environmental Database Information

Appendix C – Report Terms and Conditions

APPENDIX A


Site Walkover Photographs

Site Photographs


Project Ref: 21.1146.ERA

Site Name: Land at rear of Seftor School House, Pagham

1.




2.



- 1) Site entrance – looking S
- 2) Site entrance – looking W
- 3) Site entrance – looking E
- 4) NE corner

3.



4.




Site Photographs

Project Ref: 21.1146.ERA

Site Name: Land at rear of Seftor School House, Pagham

5.



6.




- 5) View SE
- 6) View S
- 7) View SW
- 8) View W

7.



8.



Site Photographs

Project Ref: 21.1146.ERA

Site Name: Land at rear of Seftor School House, Pagham

9.




10.



- 9) View from NE corner
- 10) Embankment along SE border (possible ACM)
- 11) View SW to Seftor Cottage
- 12) Surface debris along SE border (possible ACM)

11.



12.



Site Photographs

Project Ref: 21.1146.ERA

Site Name: Land at rear of Sefter School House, Pagham

13.




14.



15.



16.



- 9) S corner – looking at Sefter Cottage
- 13) Surface debris along SE border (possible ACM)
- 14) View NW to Sefter School House
- 15) Surface debris along SW border (fire pit)

Site Photographs


Project Ref: 21.1146.ERA

Site Name: Land at rear of Seftor School House, Pagham

17.



18.



17) Shallow excavation along NW border

18) Surface debris adjacent to excavation (fire pit)

19) Shallow excavation – looking W

20) General view W to Seftor School House

19.



20.

