Sea Estate Rustington – Proposed Tree Work 2012-13 – Edition 2

ITEM No	HOUSE NO.	ROAD NAME	TREE TYPE	WORK IDENTIFIED FOR 2012-2013	DESCRIPTION OF WORK REQUIRED
2	6	Sea Avenue	*Pine	M/S	Remove ivy from tree
3	15	Sea Avenue	*Lime	CL	Prune growth at base of tree and minor crown lift
4	17	Sea Avenue	*Lime	CL	Prune growth at base of tree and minor crown lift
6	30	Sea Avenue	*Pine	CR	**Reduce lowest limb 2m from west**
7	37	Sea Avenue	*Robinia	CR & DW	Trees in poor condition. Trim back dead wood for safety reasons and reduce crown to remove spindly growth. Review next year
8	37	Sea Avenue	*Robinia	CR & DW	
9	44	Sea Avenue	*Birch	M/S	Light trim to clear estate road
10	44	Sea Avenue	*Pine	CR	Reduce low branch residents side
13	48	Sea Avenue	*Pine	CL	Crown Lift to clear road
14	50	Sea Avenue	*Pine	CL	**Crown Lift - one limb over road to be removed**
15	47	Sea Avenue	*Pine	DW	Dead wood removal
16	52	Sea Avenue	*Pine	DW	Dead wood removal
17	52	Sea Avenue	*Sweet Chestnut	CL	Crown lift to clear garden
18	54	Sea Avenue	*Pine	CL	Remove lower limb to clear road
19	51	Sea Avenue	*Sweet Chestnut	CL & DW	**Crown lift to 5m over drive and road. Remove dead wood**
20	53	Sea Avenue	Pine	CL	Minor crown lift
23	57	Sea Avenue	*Pine	CL	**Reduce lowest limb 2m from north**
24	57	Sea Avenue	*Pine	CL	**Remove three lowest limbs**
25	59	Sea Avenue	Pine	DW	Remove lower dead limbs
26	64	Sea Avenue	*Pine	CL	Remove limb to clear drive. Disease detected - review next year
27	61A	Sea Avenue	Pine	CL	Crown lift to clear hedge
28	61A	Sea Avenue	Birch	CL	Crown lift to clear verge
29	70	Sea Avenue	*Pine	CL	Crown lift to clear road
32	65	Sea Avenue	Pine	DW	Diseased tree shows no improvement in condition and is now in very poor condition. **Remove dead wood and assess safety of tree**
34	78	Sea Avenue	*Ilex	CL	**Crown lift to 2.5m on garden side only**

Sea Estate Rustington – Proposed Tree Work 2012-13 – Edition 2

35	80	Sea Avenue	*Pine	CL	**Remove two limbs over drive to give clear access to property**
36	71	Sea Avenue	*Pine	CL	Crown lift to remove dead and dying branches
37	82	Sea Avenue	*Ilex	CL	**Crown lift 2.5m garden side only**
38	82	Sea Avenue	*Pine	CL	**Remove two lowest branches**
39	86	Sea Avenue	*Pine	-	**No work planned ADC assess as safe – review next year**
40	Op 92	Sea Avenue	Ilex	CL & CR	Reshape crown to rebalance tree. Tree is interfering with garden
41	Op 92	Sea Avenue	Macrocarpa	CL	**Remove lowest limb impinging on adjacent tree and remove two on residents side on second lowest limb** Review safety of tree next year
46	96	Sea Avenue	Pine	CL	Minor crown lift
49	Lynwood	The Thatchway	*Macracarpa	CL	Crown Lift to clear residents side and road
50	Lynwood	The Thatchway	*Macrocarpa	CL	Crown Lift to clear residents drive and road
51	Seacroft	The Roundway	*Pine	CL	Light crown lift to clear road
52	Conifers	The Roundway	*Pine	DW	Remove dead wood
53	Conifers	The Roundway	Macracarpa	CL	**Crown lift to 3m on garden side and 1m over shed roof**
56	Om House	The Roundway	*Pine	-	**Deleted planned work ADC assess as unnecessary**
59	8	The Parkway	*Pine	CL	Crown lift residents side to clear garden
60	12	The Parkway	*Pine	CL	Crown lift road side interfering with other tree
61	12	The Parkway	Pine	DW	Dead Wood removal
63	25	The Parkway	Pine	CL	**Crown Lift one branch over road and three over garden area**
65	32	The Parkway	*Pine	CL/DW	Crown lift road side and remove dead wood
68	45	The Parkway	*Pine	CL	Remove lower limb interfering with residents garden
69	36	The Parkway	*Pine	CL	**Remove tree limbs over residents garden**
70	Gate (South side)	Bushby Avenue	Sycamore	CL	Crown lift on road and residents side to clear road and garden (Note: Demise of Sea Estate being established with LA)
71	Gate (South side)	Bushby Avenue	Sycamore	CL	Crown lift to clear road (Note: Demise of Sea Estate being established with LA)
74	6	Bushby Avenue	Birch	M/S	Light trim to clear road
75	8	Bushby Avenue	*Cedar	DW	Remove dead wood
76	12	Bushby Avenue	Sycamore	MS	Remove extensive Ivy growth. Work to be undertaken in November 2012
77	Op 12	Bushby Avenue	Whitebeam	M/S	Remove rubbing branches
78	22	Bushby Avenue	Pine	-	**Remove redundant cable brace from tree - ADC assess as safe**

Sea Estate Rustington – Proposed Tree Work 2012-13 – Edition 2

79	**25/25A boundary**	Bushby Avenue	*Pine	CL/DW	**Remove two lowest branches from limb damaged by high sided lorries and dead wood for safety considerations**
80	Op 32	Bushby Avenue	Pine	CL	Minor crown lift on road and residents side
81	36	Bushby Avenue	Pine	CL	Crown lift to clear drive
82	38	Bushby Avenue	Ash	CL	Crown lift residents side to clear garden
85	3	The Bramblings	*Pine	-	**Subject to separate application**
86	5	The Bramblings	*Pine	DW	Dead wood removal
87	7	The Bramblings	*Pine	CL	Small crown lift to clear road and residents side
88	25	The Bramblings	*Norway Maple	CL	Minor crown lift to clear drive and hedge
89	3	Preston Avenue	Birch	DW	Dead Wood removal
91	19	Preston Avenue	Birch	CL	Minor crown lift to clear path
92	Entrance E	Meadway	Acer	M/S	Light trim
94	21	Meadway	*Ash	CL	Crown Lift residents side to clear path for resident
96	Littlecroft	The Close	*Pine	-	**No work planned – this appears to have been mis-identified with another tree near this location**
97	Opp Seaward	The Close	*Pine	-	**No work planned – review next year**

KEY: **CL** – RAISING OF LOWER LIMBS, **CT** – REMOVAL OF INTERNAL LIMBS, **CR** – REDUCTION OF OVERALL SPREAD
POL – POLLARD HARD CROWN REDUCTION, **DW** – REMOVAL OF DEAD WOOD, **FELL** – TAKING DOWN OF ENTIRE TREE
PTL – POSSIBLE TREE FELL, **M/S** – MISCELLANEOUS WORK
* DENOTES TPO (TREE PRESERVATION ORDER)

NOTE: ITEMS IN BOLD TYPE ARE ALTERATIONS FROM PREVIOUS APPLICATION FOLLOWING ADC COMMENTS