

Julian Munn Drainage Services Ltd

10 Drygrounds Lane, Bognor Regis, West Sussex, PO22 8PS



CCTV Survey

Address: Sainsburys Store, Rustington

Job No.S0477/09/13

Client: Barr Ltd

Week Ending Friday, 04/10/13

Site: Sainsbury Rustington


My Manager: **John Solomon**


[illegible]

[illegible]


30/09/13

Sgt. Oakes
West to Sand







DRAINAGE TOWARDS DARLING




DRAINAGE OF DRAIN FROM BOUNDARY




SECTION OF PIPE X FROM M




FILLED IN DITCH LINE (2)




FILLED IN DITCH LINE (3)




FILLED IN DITCH LINE (4)




FILLED IN DITCH LINE (5)




FILLED IN DITCH LINE




VERT OF FILLED IN DITCH (1)




VERT OF FILLED IN DITCH (2)




VERT OF FILLED IN DITCH (3)




MH 01 (2)




MH 01



SOIL AND CHALK IN PART 1



EXCAVATION OF POINT AT 26.8



PART EXCAVATION TO REACH