

3 Mill Lane, Rustington, Littlehampton, Arun, West Sussex, BN16 3JN

The tree in question is mature macrocarpa located in the front garden of the above property. adjacent to the tree is the annex of the property and it is located just four metres away this annex was originally installed on the property in the 1970s but was originally a garage. in recent years there has been a loss of issues with evidence of subsidence an now there is a large root growing through the ground of the annex which is causing major issues to the structure the proposed works we would be applying for would be to remove the entire tree to ground level, then to re plant with something of a similar species but not as close to their property. we have a structural surveyors report attached to the document which provides evidence of the above and much more.

