

9 Walberton Park PHOTOGRAPHS



View of the Patio and replacement Privacy Screen. North West Corner, Facing North

2.



View of the low boundary Wall with replacement Privacy Screen affixed. West boundary of the patio, North end, facing North West



View of the Patio boundary Wall and Privacy Screen, North West side, facing East



View of the North Patio boundary Wall and Privacy Screen, facing South.

5



View of the southern part of the West patio boundary overgrown as the remainder was. Looking South.

6



View of the Patio and replacement Privacy Screen, North West Corner, Facing North. The same as in photograph 1 with an impression of the former vegetation growth, since removed