

14th July 2021

Y/44/17/OUT - Outline Planning Conditions submission doc

Y/44/17/OUT: 70-units						
DRAWING TITLE		REVISION				
Condition 6 - TREES						
	Site Visit Record Sheet between Project Arboriculturist and ADC Tree Officer	-	~			
	Cover Letter_DoC 6_ ARB					
CONDITION 11 – CONTAMINATION						
	Ground Investigation Interpretive Report - A112666	-	..			
	Stakers Farm-Asbestos Demolition Survey Report – 2019 - 00565 V1	V1	V1			
	191107 Gas Monitoring Results GE003T00527 07_Nov_2019 07_54	-	~			
	191119 Gas Monitoring Results GE002802831 19_Nov_2019 11_30	-	~			
	191120 Gas Monitoring Results GE003T00545 20_Nov_2019 05_49	-	..			
	191206 Gas Monitoring Results GE003T00560 06_Dec_2019 05_08	-	~			
	191216 Gas Monitoring Results GE003T00566 16th Dec 2019	-	~			
	200102 Gas Monitoring Results GE003T00573 02_Jan_2020 06_06	-	~			
	200116 Gas Monitoring Results GE003T00573 16th Jan 2020	-	..			
	200131 Gas Monitoring Results GE005800126 31st Jan 2020	-	~			
	200207 Gas Monitoring Results GE004D00599 7th Feb 2020	-	~			
	200213 Gas Monitoring Results GE004D00604 13 Feb 2020, 06_55	-	~			
	200213 Gas Monitoring Results GE004D00604 13th Feb 2020	-	..			
	200227 Gas Monitoring Results GE003T00656 27th Feb 2020	-	..			
	200228 Yapton - GESL GE18875 Additional BRE 365 Soakage Testing	-	~			
	200312 Gas Monitoring Results GE005B00095 12th Mar 2020	-	~			
	200326 Gas Monitoring Results GE005B00105	-	..			
	200331 Yapton - GESL GE18965 Additional BRE 365 Soakage Testing	-	~			

Cover Letter_DoC 11 GI						
North End Road, Yapton RAMS	-	-				