



Groundwater Monitoring Record

Project: Land at Bilsham Road, Yapton
Client: Gleeson Developments
Project No: BRD2693

Borehole name	Date	Monitored by (initials)	Borehole depth (m)	Qty free product detected (mm)	Groundwater level below ground surface (m)	Groundwater level below top of standpipe (m)	Amount purged (l)	Post purge groundwater level below top of standpipe (m)	Comments
WS02	22/02/2018	NK	3.96	n/a	0.48	0.37	n/a	n/a	No odour noted on retrieval of interface meter.
WS03	22/02/2018	NK	4.02	n/a	1.54	1.38	n/a	n/a	No odour noted on retrieval of interface meter.
WS04	22/02/2018	NK	3.97	n/a	1.82	1.69	n/a	n/a	No odour noted on retrieval of interface meter.
WS07	22/02/2018	NK	3.83	n/a	1.00	0.87	n/a	n/a	No odour noted on retrieval of interface meter.
WS08	22/02/2018	NK	3.83	n/a	1.26	1.14	n/a	n/a	No odour noted on retrieval of interface meter.
WS09	22/02/2018	NK	3.98	n/a	1.23	1.09	n/a	n/a	No odour noted on retrieval of interface meter.
WS10	22/02/2018	NK	3.87	n/a	1.57	1.41	n/a	n/a	No odour noted on retrieval of interface meter.