



Groundwater Monitoring Record

Project: Land at Bilsham Road, Yapton
Client: Gleeson Developments
Project No: BRD2693

Borehole name	Date	Monitored by (initials)	Borehole depth (m)	Qty free product detected (mm)	Groundwater level below ground surface (m)	Groundwater level below top of standpipe (m)	Amount purged (l)	Post purge groundwater level below top of standpipe (m)	Comments
WS02	24/01/2018	NK	3.95	n/a	0.44	0.33	n/a	n/a	No odour noted on retrieval of interface meter.
WS03	24/01/2018	NK	4.01	n/a	1.09	0.93	n/a	n/a	No odour noted on retrieval of interface meter.
WS04	24/01/2018	NK	3.97	n/a	1.29	1.17	n/a	n/a	No odour noted on retrieval of interface meter.
WS07	24/01/2018	NK	3.83	n/a	0.87	0.74	n/a	n/a	No odour noted on retrieval of interface meter.
WS08	24/01/2018	NK	3.83	n/a	0.89	0.77	n/a	n/a	No odour noted on retrieval of interface meter.
WS09	24/01/2018	NK	3.98	n/a	1.14	1.00	n/a	n/a	No odour noted on retrieval of interface meter.
WS10	24/01/2018	NK	n/a	n/a	n/a	n/a	n/a	n/a	Under a large puddle so was unable to get measurements.