

Drainage CCTV Survey Report

Coastal Drains Ltd

Produced using Pipe Navigator software. www.pipenavigator.com

Drainage CCTV Survey Report

Coastal Drains Ltd

Unit 3, Wayside, 7 Commerce Way, Lancing Business Park, Lancing, West Sussex, BN15 8SW

Survey No. : **1074**

Survey Date : **02/05/2017**

Survey Time :

Customer

**Mrs Roberts
38 Cherry Avenue
Yapton
Arundel
West Sussex
BN18 0LB**

Phone No. : **07962242215**

Contact :

Site

**38 Cherry Avenue
38 Cherry Avenue
Yapton
Arundel
West Sussex
BN18 0LB**

Purpose of Survey

Investigation

Surveyor No. : **002**

Surveyor Name : **Gary Taylor**

Weather : **Dry**

Your Reference :

Insurance Claim Ref. :

Our Other Ref. :

Survey No. : 1074 Survey Date : 02/05/2017 Survey Time :
Customer Name : Mrs Roberts
Site : 38 Cherry Avenue

*** Start of Sections ***

Section : 1074-1 Downstream from S/W downpipe to S/W M/H in next door : N
Length : 4.78 mtrs Pipe Material : UPVC Shape : Circular
Depth : 0.00 mtrs Pipe Size : 100 mm Duty : Storm
Location :
Conclusion :
There are no defects in this run.

*** End of Sections ***

Survey No. : 1074 Survey Date : 02/05/2017 Survey Time :
 Customer Name : Mrs Roberts
 Site : 38 Cherry Avenue






*** Start of Sections ***

Section : 1074-1 *Downstream from S/W downpipe to S/W M/H in nextdoor*

Length : 4.78 mtrs Pipe Material : UPVC Shape : Circular
 Depth : 0.00 mtrs Pipe Size : 100 mm Duty : Storm
 Video : N

Observations

Position (mtrs)	Code	Details
	OV	overview of downpipe
	OV	overview of 38 Cherry Avenue
0.00	ST	Start of Survey Section
0.53	JN	Junction serving SW Downpipe
0.53	MC	Material of drain/sewer changes to VC at this point
4.78	END	End of survey section S/W MH in next door




Conclusion :

There are no defects in this run.

Survey No. : **1074** Survey Date : **02/05/2017** Survey Time :
 Customer Name : **Mrs Roberts**
 Site : **38 Cherry Avenue**

Schematic Diagram for Section 1074-1



Photos

There are no Photos for this section.

*** End of Sections ***

Drainage CCTV Survey Report

Coastal Drains Ltd

Unit 3, Wayside, 7 Commerce Way, Lancing Business Park, Lancing, West Sussex, BN15 8SW

Phone : 01903 766353 Fax :

Survey No. : **1074**

Survey Date : **02/05/2017**

Survey Time :

Customer Name : **Mrs Roberts**

Site : **38 Cherry Avenue**

Written Summary

No recommendations as no defects found.

Site Plan

Customer Name : Mrs Roberts
Site : 38 Cherry Avenue

