

Yapton Free Church

Percolation Test Results

Friday 10 November 2017

Test 1		Test 2		Test 3	
Time (min)	Depth to water (mm)	Time	Depth to water (mm)	Time	Depth to water (mm)
1005	205	1440	000		
1010	245	1445	15		
1015	280	1350	30		
1020	310	1355	36		
1025	340	1400	50		
1030	370	1405	58		
1035	385	1410	70		
1040	400	1415	80		
1045	415	1420	90		
1050	430	1425	100		
1055	440	1430	108		
1100	450	1435	116		
1105	460	1440	120		
1110	470	1445	128		
1115	480	1450	135		
1120	490	1455	142		
1125	500	1500	150		
1130	520	1505	156		
1135	530	1510	166		
1140	540	1520	187		
1145	550	1530	202		
1150	560	1540	221		
1200	570	1550	242		
1210	580	1600	259		
1220	590	1610	261		
1230	610	1620	272		
1240	620	1630	283		
1250	630	1645	305		
1300	640	1700	330		
1310	660	1715	334		
1320	670	1730	363		
1330	680	1745	370		
		1800	388		
		1815	405		
		1830	415		

Yapton Free Church

Percolation Test Results

Friday 10 November 2017

Continued:

Test 1		Test 2		Test 3	
Time (min)	Depth to water (mm)	Time	Depth to water (mm)	Time	Depth to water (mm)
		1845	430		
		1900	445		
		1915	458		
		1930	470		
		1945	482		
		2000	493		
		2015	503		
		2030	512		
		2045	423		
		2100	532		
		2115	543		
		2130	553		
		2145	562		
		2200	571		
		2215	580		

Size of pit 700mm x 1500mm x 900mm deep

Location: 10 metres from external wall of building