

Potting Barn. Photos



Existing 1.8m close boarded timber fence



0.9mm timber cleft chestnut fence changed to 1.8m close boarded timber fence



0.9mm timber cleft chestnut fence changed to 1.8m close boarded timber fence



Existing 1.8m timber fence and gate repositioned



Existing dummy door and infill under window replaced with face brick to match existing.




Existing gate and fence to be repositioned.

New fence to match



Aerial

Site



Historic Aerial

1.8m fence